



WK20-ZM rear nut mount socket assembling instructio-Solder



4、Tighten the lock nut by torque of 0.6-1N.m.



5、 Strip the cable to the length shown in the table below, and solder the wire to the pin .Note that the soldering iron should not burn the pin during the process. After soldering, put a heat shrink tubeon the solder pin and wrappen the heat shrink tube.



\cdot Strip length

